

## **STEPS**

- 1 ASSURE THAT ALL ELECTRICAL POWER IS TURN OFF TO FIXTURE.
- 2 REMOVE OUTER CHANNEL FROM INNER CHANNEL.
- 3 MOUNT INNER CHANNEL TO WALL SURFACE WITH MOUNTING SCREW BY OTHERS.
- 4 MAKE WIRE CONNECTIONS FROM OUTER CHANNEL TO SUPPLY WIRES.
- 5 MOUNT OUTER CHANNEL TO INNER CHANNEL USING 8-32 HEX CAP NUTS.
- 6 MAKE CERTAIN WIRES STAY WITHIN INNER CHANNEL WHEN INSTALLING OUTER CHANNEL.
- 7 INSTALL LAMPS. (BY OTHERS)
- 8 TURN ON POWER TO FIXTURE.

## **VS STRIP INSTALLATION**

<u> </u>	_	C.W. COLE	<b>E &amp; CO., INC.</b> 2560	N. ROSEMEAD	BLVD., SOUTH EL	. MONTE, CA. 91733-1593	www.colelighting.com	• (626) 443-2473	• FAX (626) 443-9253
lui §	191	VS	MIRROR LIGHT			1-28-13 E.V.			
I His	NCE	<b>V</b> 13							
<b>1</b> 3 ?	S SI								
	<b>-</b> ≥								
$\mathbf{I}(\mathbf{C})$	된	DRAWN BY		CHECKED BY		SCALE	DRAWING No	K2412-	VS-IS
		DTW	10-24-12	D.W.	10-24-12	1/4" = 1"		174714-	4 D-10

INFORMATION AND DESIGNS HEREON ARE PROPRIETARY AND CONFIDENTIAL. THEY MAY NOT BE USED OR REPRODUCED WITHOUT THE EXPRESSED PERMISSION OF C.W. COLE & CO. IN